Work Orde	er ID 110759 3:02:46 PM		*11	0759*		,					Page 1
Revision ID: Item Name:	D3564-9 Stainless Steel Wearplate Fwd		Accept	*N900		100	*	Setup	Start Stop	*N!	S1* S2*
Start Date: Required Date: Reference:	1/07/14 Start Qty: 12.0 Req'd Qty: 12.0		*18*	Cust Item 1 Customer:	ID:						
Approvals:	Process Plan: MLJ		Tooling: SPC (Y/N):		ate:			Run	Start Stop	*N *N	
Sequence ID/ Work Center II	Operation D Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr							4			
D3564	Rev D										
*100 *100* Waterjet FLOW CNC Waterj		per Dwg D3564 *****(D356	0.00 0.00 54-1F)*****Dwg Rev	: > _Prog			18	<u> </u>			<u>Ae</u> 14.01.27
110	QC2- Inspect parts of	f machine FAI/FAIB	0.00								
110 QC Quality Control	Memo		0.00				18		<u>ی</u>		Ac 14.01.2
120 *120*	QC8- Inspect parts -	second check	0.00 DAS				(x15	\	•		
QC Quality Control	Мето		0.00 9-89	14/01/27		•	A10	J			

A. A.

DQA:			Date:											
						WORK ORDER NON	-CC	ONFO	RMANCE / U	PDATE				AEROSPACE
QA Closed:			Date:								Wd	ork Order up	date only	
Work Orde	er:					DISPOSITION				AGAINST	DEI	PARTMENT	PROCESS	
, violik Grak	-				_	Rework	1		Skid-tube	Crosstube			Water Jet	Engineering
Part N	lo.					Scrap	1		Machining	Small Fab		Pro	d. Eng. Coor.	Quality
	•				_	Use-as-is	1	Thern	noforming	Finishing		Rec/Stor	e/Packaging	Other
NCR N	۱o.					Suspected Unapproved]		Large Fab	Composite			Supplier	
					-									
Root					Desc	ription of work order update		nitial		tion		Sign &		
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Desc	ription		Date	Verification	QC Inspector
Design									9					
Doc/Data	-													
Equip/Tooling	\dashv													
Handling/Pre	Н													
Material	\dashv						ļ							
Operator Offset/Setup														
Process	H													
Supplier														
Training									1					
Transport														
Unapproved			1						ļ					
			<u> </u>		•	•	FA	ULT CA	TEGORY	-				
Landi	ng (Gear				General								
		Bending				Bend		Folio/F	Program			Outside Dim	ensions	Pressure/Forced
		Centre No	ot Concer	ntric		BOM/Route		Grain				Over/Under	tolerance	Set-up
		Cracks				Broken/Damage/Defect		Hardwa	are			Part Incorre	-	Temperature/Cure
		Crimp/Kir	nk/Ripple	/Wave		Burrs		Inspect	ion Incomplete/U	Inqualified		Part Lost/Mi		Weld
		Cuffs				Contamination		4	tions Incomplete/			Part Moved		Wrong Stock Pulled
	_	Crushing				Countersink		-1 '	gned/off center		<u> </u>	Positioned V		¬ .
	ldash	Heat Trea				Cut Too Short	\vdash	Mislabe				Power Loss/	Surge	Other
İ	<u> </u>	Inspectio		Tube	<u> </u>	Drawing		Misrea						
ŀ	_	Marks/Ch				Drill Holes	 	Off-set						
	$oxed{oxed}$	Turning S			\vdash	Finish	<u> </u>	-	Calibration					
	1	Wave/Tw	ist in Tub/	oe -		Fit/Function		Out of	Sequence					

Work Orde		0759			*11(759*						Page 2	
Item ID: Revision ID:	D3564-9				Accept	*N900	<u>040</u>	1.00)* s	etup Star	*N	S1*	
Item Name:	Stainless Stee	l Wearplate Fwd								Stop	*N	S2*	
Start Date:	1/07/14	Start Qty: 12.00		*12*		Cust Item	ID:						
Required Date:	1/07/14	Req'd Qty: 12.00		*12*		Customer:							
Reference:									_	, a			
Approvals:	Process Pla	nn:	Date:		Tooling:	D	ate:		R	tun Star	^!\ <u>\</u>	R1*	
			Date:		SPC (Y/N):	D	ate:			Stop	, *N	R2*	
Sequence ID/ Work Center I	D	Operation Description		· · · · · ·	Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
130 *120* Brake NC		NC BRAKE			0.00		D/ 3(כ	18			14/01/29	
Brake NC					per Dwg D3564 using Ji 4 on brake using Jig D		9-8	9					
					DAS 27								
140		QC5- Inspect part comple	eteness to s	tep on W/O	0.00 9-89				10)				
140 QC		Memo			0.00 1411	30			18_				
Quality Control		Ensure joggl	e as per dw	g D3429								;	
150					0.00				/			<i>te</i> .	
150		Large Fab							18			14-03- 18L	13
Large Fab Large Fab		Memo Oty Desc	ription	Ratel	0.00 hA/R 2059B Hai	rdcoat "						156	,
LAIGU LAU				Dates coat as per Dwg		ucoat						/	

DQA:			Date:						_				7	TRACT
						WORK ORDER NON-	-CC	ONFO	RMANCE / UPDATE			–	_	AEROSPACE
QA Closed:			Date:							W	ork Order up	date only		-
Work Orde	er:					DISPOSITION		g* *	AGAIN	ST DE	PARTMENT	/PROCESS		
	-					Rework			Skid-tube Crosstu	be	7	Water Jet	7 6	ngineering
Part N	lo.					Scrap			Machining Small F	_	Pro	d. Eng. Coor.	1	Quality
	-			•	_	Use-as-is			noforming Finishi	ing	-1	re/Packaging	1	Other
NCR N	lo.			<u>.</u>		Suspected Unapproved		,	Large Fab Compos	ite		Supplier		
	_		<u> </u>	-					A - 1 - 2 - 2		C: oʻ		_	
Root		. .	.	۵.	Desci	ription of work order update		nitial	Action		Sign &	Manifiantian		OC Imamastan
Cause	_	Date	Step	Qty		or non-conformance	Cn	ief Eng	Description		Date	Verification	+	QC Inspector
Design	\dashv													
Doc/Data							ŀ							
Equip/Tooling Handling/Pre	\exists													
Material	\dashv													
Operator									·					
Offset/Setup														
Process														
Supplier	Н													
Training		•												
Transport														
Unapproved							<u> </u>						<u> </u>	
							FA	ULT CA	ΓEGORY					
Landi	ng (ear				General		_			_	_	_	
		Bending				Bend		Folio/F	Program	L	Outside Dim	ensions	Pr	essure/Forced
		Centre No	ot Concer	ntric		BOM/Route	<u> </u>	Grain			Over/Under	. –	┥	et-up
		Cracks			<u> </u>	Broken/Damage/Defect	L	Hardwa			Part Incorre	<u> </u>	_	mperature/Cure
		Crimp/Kii	nk/Ripple	/Wave	<u> </u>	Burrs	<u> </u>	1 '	ion Incomplete/Unqualified	<u> </u>	Part Lost/Mi			eld
	L	Cuffs			_	Contamination	L	4	tions Incomplete/Unclear	<u> </u>	Part Moved		_Jw	rong Stock Pulled
	Ĺ	Crushing			_	Countersink	-	1 '	gned/off center	<u> </u>	Positioned V	_	- 1 -	
	_	Heat Trea			\vdash	Cut Too Short	\vdash	Mislabe		L	Power Loss/	Surge	lOt	ther
		Inspectio		Tube	<u> </u>	Drawing	\vdash	Misrea						
	_	Marks/Ch			 	Drill Holes		Off-set						
	<u> </u>	Turning S			ļ	Finish	\vdash	4	Calibration			 		
1	l	Wave/Tw	ist in Tul	oe –	ļ	Fit/Function	1	Out of:	Sequence					

Work Ord January-07-14		0759		*110	759*						Page 3
Item ID: Revision ID: Item Name:	D3564-9 Stainless Stee	l Wearplate Fwd		Accept	*N90	იი4ი	100)* s	setup Start	1 1	S1* S2*
Start Date: Required Date Reference:	1/07/14 :: 1/07/14	Start Qty: 12.00 Req'd Qty: 12.00	*1 <i>9</i> * *1 <i>9</i> *		Cust Ite Custome				G.		
Approvals:	Process Pla	nn:	Date:	Tooling: SPC (Y/N):		Date:		. В	Run Start Stop	^IV	R1* R2*
Sequence ID/ Work Center I	ID	Operation Description QC10- Inspect visual per	OSI004- ground welds	Set Up/ Run Hours	Tool II	D Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
160 QC Quality Control		Мето		0.00	Ģ.			_/8_		14-31	<u> </u>
170 *170* QC Quality Control		QC5- Inspect part comple	eteness to step on W/O	0.00				(3)	<u> 14.0</u> 3	5-13	DAS 9 9-89
180 *1 A \ * Powder Coating		Memo START ŢIM	5028	0.00 0.00 OVEN TEMPERATURI 32	E:			. [8	3		mml)

DQA:			Date:												7
						WORK ORDER NON	-CC	ONFO	RMANCE / U	IPDATE			_	AEROSPACE	i E
QA Closed:			Date:							<u> </u>	Wor	k Order up	date only		
Work Orde	er:					DISPOSITION				AGAINST [DEP	ARTMENT/	PROCESS		
	-				_	Rework		i	Skid-tube	Crosstube			Water Jet		
Part N	10.					Scrap			Machining	Small Fab	4		d. Eng. Coor.	Quality	
NCR N	۱o. ِ					Use-as-is Suspected Unapproved]		noforming Large Fab	Finishing Composite		Rec/Stor	e/Packaging Supplier	Other	
Root					Desci	ription of work order update		nitial	Ac	tion		Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Desc	ription		Date	Verification	n QC Inspector	
Design Doc/Data															
Equip/Tooling	\neg														
Handling/Pre															
Material															
Operator															
Offset/Setup															
Process												:			
Supplier													!		
Training		•													
Transport									İ						
Unapproved															
	,						FA	ULT CA	TEGORY						
Landi	ng (Gear				General		,		F					
	L	Bending				Bend		4	Program	ļ	—╡	Outside Dim		Pressure/Forced	
	<u> </u>	Centre No	ot Concer	ntric		BOM/Route		Grain		1	-	Over/Under	i	Set-up	
		Cracks			<u> </u>	Broken/Damage/Defect		Hardwa		ļ		Part Incorrec		Temperature/Cure	
	<u> </u>	Crimp/Kir	nk/Ripple	/Wave		Burrs		- '	ion Incomplete/L	· · · · · · · · · · · · · · · · · · ·	_	Part Lost/Mi	-	Weld	
		Cuffs				Contamination		┥	tions Incomplete	-	_	Part Moved		Wrong Stock Pulled	
		Crushing				Countersink	\perp	-1	gned/off center	·		Positioned V	_		
		Heat Trea				Cut Too Short	L	Mislab			F	Power Loss/	Surge	Other	
		Inspectio		Tube	_	Drawing		Misrea			_				
		Marks/Ch				Drill Holes	_	Off-set			_				
		Turning S	equence			Finish	\perp	Out of	Calibration		_				
		Wave/Tw	ist in Tub	oe -	Į.	Fit/Function		Out of	Sequence						

Work Ord January-07-14	er ID 110759 3:02:46 PM			*110	759*						Page 4
tem ID: Revision ID: tem Name:	D3564-9 Stainless Steel Wearpl	late Fwd		Accept	*N900	040	100)* s	etup Start Stop		S1* S2*
Start Date: Required Date Reference:		t Qty: 12.00 d Qty: 12.00	*1 <i>9</i> * *1 <i>9</i> *		Cust Item II Customer:	D:					
Approvals:	Process Plan:		Pate:	Tooling: _ SPC (Y/N):		ite:		R	Run Start Stop	^I\]	R1* R2*
Sequence ID/ Work Center I 190 *1 QA* QC Quality Control		ation ription Inspect Part Finish Memo		Set Up/DAS Run Hours 0.00 9-89 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
* >^^* Packaging Packaging	Identif	y as per dwg & Stock 1	Location: FP-66	0.00				x18		_ Al	10/03/2
210 *210* QC Quality Control	QC21-	Final Inspection - Wor	rk Order Release	0.00					All DILIC	1-03-17 53-17	7 }_

DQA:			Date:											•	DART
QA Closed:			Date:			WORK ORDER NON-	-CC	ONFO	RMANCE / U		Wark O	rder ur	odate only		AEROSPACE
QA Closed.			Date.				-1				WOIR O	aci u	saute only		
Work Orde	er:					DISPOSITION				AGAINST I	DEPART	MENT	/PROCESS		
	•					Rework	1		Skid-tube	Crosstube			Water Jet		Engineering
Part N	lo.					Scrap		1	Machining	Small Fab		Pro	d. Eng. Coor.		Quality
	•					Use-as-is			noforming	Finishing	R		re/Packaging	╗	Other
NCR N	١o.					Suspected Unapproved			Large Fab	Composite			Supplier	╗	
	•						•		- _						
Root					Desc	ription of work order update	١	nitial	Ac	tion	Sig	gn &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Desc	ription	D	ate	Verification		QC Inspector
Design															
Doc/Data							ļ	•						İ	
Equip/Tooling															
Handling/Pre															
Material													1	İ	!
Operator									ļ						
Offset/Setup															
Process															
Supplier											l				
Training											ļ				
Transport											İ				
Unapproved															
							FA	ULT CA	TEGORY			***			
Landi	ng (Gear			_	General		٦		r			F	_	
		Bending			<u> </u>	Bend		4 '	Program		_		nensions	-	Pressure/Forced
		Centre No	ot Concer	ntric		BOM/Route	<u></u>	Grain		ļ	 i		tolerance	_	Set-up
		Cracks				Broken/Damage/Defect		Hardwa				Incorre	1		Temperature/Cure
		Crimp/Kir	nk/Ripple	:/Wave		Burrs		Inspect	ion Incomplete/U	Inqualified		Lost/M			Weld
		Cuffs			L	Contamination		4	tions Incomplete,		—-	Moved			Wrong Stock Pulled
		Crushing			<u> </u>	Countersink	<u>_</u>	-1	gned/off center	ļ	_	ioned \	r		l .
		Heat Trea				Cut Too Short	\vdash	Mislabe			Pow	er Loss/	'Surge		Other
	_	Inspectio	· ·	Tube		Drawing	\vdash	Misrea							
]		Marks/Ch			<u> </u>	Drill Holes	<u>_</u>	Off-set		•					
	L	Turning S	=			Finish	L	4	Calibration						
		Wave/Tw	ist in Tub	эе		Fit/Function		Out of	Sequence						

Required Date: 1/07/14

Required Qty: 12.00

January-07-14 3:02:45 PM

Work Order ID:

110759

Parent Item:

D3564-9

Parent Item Name:

Stainless Steel Wearplate Fwd

Comments:

IPP Rev:A

New Issue 07-03-08 ec

IPP Rev:B

As per Rev C 07-07-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location		Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S16GA 304/316 Sheet .063		Purchased	No			100	sf	330.8470	1.41	<u> 17.81052</u>	6-Ac	14.0	1.2
				Location		Loc Oty	<u>Lo</u>	c Code					
				MAT020		330.847							
					M126915	10.847						, 0	d.
					M127821	320			16	17821		10	. τ

Start Date: 1/07/14

Start Qty: 12.00

DQA:			Date:											'SAG	7
						WORK ORDER NON	-CC	ONFO	RMANCE / U				–	AEROSPAC) E
QA Closed:			Date:								Wo	ork Order up	date only		
Work Orde	er:					DISPOSITION				AGAINST	DEI	PARTMENT	PROCESS		
	-					Rework	1		Skid-tube	Crosstube			Water Jet	Engineering]
Part N	lo.					Scrap		1	Machining	Small Fab		Pro	d. Eng. Coor.	Quality]
	-					Use-as-is	1	Thern	noforming	Finishing		Rec/Stor	e/Packaging	Other]
NCR N	10.					Suspected Unapproved]		Large Fab	Composite			Supplier]
									 					·	
Root					Desc	ription of work order update		nitial		tion		Sign &			
Cause	_	Date	Step	Qty		or non-conformance	Ch	ief Eng	Desc	ription		Date	Verification	QC Inspector	
Design	_	i													
Doc/Data	_								·						
Equip/Tooling															
Handling/Pre		:							<u> </u>						
Material															
Operator	\square														
Offset/Setup	Н								:						
Process									:						
Supplier									1				i		
Training															
Transport													•		
Unapproved			1	<u> </u>	1		FΑ	ULT CA	regory			<u> </u>			
Landi	ng (ear				General								· ······	
		Bending				Bend]Folio/F	Program			Outside Dim	ensions	Pressure/Forced	İ
		Centre No	ot Concer	ntric		BOM/Route		Grain	J			Over/Under	tolerance	Set-up	
		Cracks				Broken/Damage/Defect		Hardwa	are			Part Incorred	cí 📙	Temperature/Cure	e
		Crimp/Kir	nk/Ripple	/Wave		Burrs	Г	Inspect	ion Incomplete/L	Jnqualified		Part Lost/Mi	ssing	Weld	
}		Cuffs				Contamination		Instruc	tions Incomplete	/Unclear		Part Moved		Wrong Stock Pulle	∍d
		Crushing				Countersink		Misali	gned/off center			Positioned V		<u> </u>	
		Heat Trea	at			Cut Too Short		Mislabe	eled			Power Loss/	Surge	Other	
		Inspectio	n Strip in	Tube		Drawing		Misrea	d					W.,	
		Marks/Ch	natter			Drill Holes		Off-set							
		Turning S	equence			Finish		Out of	Calibration						
		Wave/Tw	ist in Tub	oe -		Fit/Function		Out of	Sequence						

DART AEROSPACE LTD	Work Order:	110759
Description: Wearshoe	Part Number:	D3564-9
Inspection Dwg: D3564 Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.227	+/-0.010	3.227	~		V	JKm-05
2.432	+/-0.010	2.437	-		>	
2.50	+/-0.030	2.50	-		· ·	
6.000	+/-0.010	6.000	_		7	J×m-06
12.104	+/-0.010	12.104			T	
18.000	+/-0.010	18.000			7	
18.000	+/-0.010	18.000	-		Τ	
18.00	+/-0.030	18.00	(Τ	
9.00	+/-0.030	9.00	_		7	
11.50	+/-0.030	11.50	-		T	
0.300 x 0.300	+/-0.010	.300 x 300			V	
Ø0.188	+0.005/-0.001	381,	-		✓	
R0.375	+/-0.010	,375	-		RG	
0.063	+/-0.010	.060	_		V	
					The state of the s	


Measured by:	Audited by: DAS	Prototype Approval:	N/A
Date: 14.01.	27 Date: 16	14/4/27 Date:	N/A


Rev	Date	Change	Revised by	Approved
A (08.01.16	New Issue	KJ/EC/DD	77

	現である。 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1	
			<i>e</i> • •	
	•			
			:	
-			:	
ţ)				
.	•			
i i				
, , ,				
ř.			1	
î.				- 1
				- 3
i				
f I				
i ∰				
5				
Š.				
÷ ↓				
9. \$5				
į.			:	
£.				
5- 			į.	
7e {				
\$. \$.,				
				- 1
Age Age				-
1, 2, 2, 2,				-
				-
		•		-
Ìò.				
v.				
¥				
).				
.			i	
<u> </u>				
2 8	•			
£ .				
i i s				
K .				
?				
			1	
}				
	•			
5- b.				
5. B				
Å				
<u> </u>				
¥.				
Carlo Carlo	per all many many titles of the control of		i	



			4 - 10 4 - 10 5 - 1
C. manufactural de l'altra de l'a			
100 100 100 100 100 100 100 10			
Reading to the second of the s	•		
A COMPANY OF THE PROPERTY OF T			
S. Carlos Saladas		•	
The state of the s			
3.00			
			; :
A Company of the Comp			
Managara de la companya de la compan			
is dividing			
The control of the co	All the second of the second o		





	- प्रतिकृति क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्षेत्र क्ष			•		4.
						≠ ₹ 9
k.						
	*				•	
	. *			•		
						:
						; ;
						!
					•	
						1
		•				
(2) (2) (3) (4) (4) (4) (4)						
機能が必要						
		٠				- 4
			•			
						- II - All All All All All All All All All A
を で で で で で で で で で で で で で				•		
			<u>.</u>			
				- Line and the second s		
*						
इतिकास के प्राप्त कर किया है।						
The state of the s						
		× .	9			
						علمنا